

Toll Free 1-800-247-6567



INNOVATIONS "In Agriculture"

**GRIP-RITE**  
CYLINDER DEPTH STOP

- HOME
- WHY GRIP-RITE
- GRIP-RITE DEPTH STOP BLOCKS
- "O" MODEL DEPTH STOP BLOCKS
- CHAIN TIGHTENERS
- CONTACT US




## CHAIN TIGHTENERS

**PLASTIC CHAIN TIGHTENER / WEAR BLOCK** for replacement of idler pulley on farm equipment.

- Decreases block replacement
- Reduces chain wear & friction
- Saves labor, money & downtime
- Increases chain life & keeps chain tight
- Lasts 4-5 times longer than woon blocks

This plastic wear block has characteristics that are very high in lubricating which reduces chain wear. After several years of continuous testing, this type of plastic has shown outlasting capabilities replacing chain sprocket idlers on all types of machinery. As well as being used on the earlier models of Gleaner combines, we have had excellent success with them on the more recent models where idler bearing pulleys and sprockets are now. This has reduced repair costs since the cost is considerably lower than current idler bearings.

To find a dealer or distributor near you, please call us toll free at [1-800-247-6567](tel:1-800-247-6567).



[Click here to view wear test results](#)